

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments
1	IS&R	L1	0	("fixedadj electrode and movable leadj electrode"). PN.	US- PGPUB ; USPAT ; DERWE NT	2004/12/0 6 10:28	
2	BRS	L2	769	fixed adj electrode and movable adj electrode	USPAT	2004/12/0 6 10:28	
3	BRS	L3	1975	fixed adj electrode and movable adj electrode	US- PGPUB ; USPAT ; DERWE NT	2004/12/0 6 10:28	
4	BRS	L4	8	3 and movable adj electrode with "single-crystal silicon"	US- PGPUB ; USPAT ; DERWE NT	2004/12/0 6 10:57	
5	BRS	L5	1	4 and signal adj Fetch\$3	US- PGPUB ; USPAT ; DERWE NT	2004/12/0 6 10:59	
6	BRS	L6	0	4 and signal adj Detect\$3	US- PGPUB ; USPAT ; DERWE NT	2004/12/0 6 11:00	
7	BRS	L7	0	4 and signal adj detect\$3	US- PGPUB ; USPAT ; DERWE NT	2004/12/0 6 11:00	

	Error Definition	Err ors
1		
2		
3		
4		
5		
6		
7		

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments
8	BRS	L8	76	3 and signal adj detect\$3	US- PGPUB ; USPAT ; DERWE NT	2004/12/0 6 11:00	
9	BRS	L9	17	3 and signal adj detector	US- PGPUB ; USPAT ; DERWE NT	2004/12/0 6 11:00	
10	BRS	L10	0	"19" and signal adj detect\$3 with high adj corrosion	US- PGPUB ; USPAT ; DERWE NT	2004/12/0 6 11:01	
11	BRS	L11	0	"19" and signal adj detector with high adj corrosion	US- PGPUB ; USPAT ; DERWE NT	2004/12/0 6 11:01	
12	BRS	L12	0	9 and signal adj detector with high adj corrosion	US- PGPUB ; USPAT ; DERWE NT	2004/12/0 6 11:01	
13	BRS	L13	0	8 and signal adj detector with high adj corrosion	US- PGPUB ; USPAT ; DERWE NT	2004/12/0 6 11:02	

	Error Definition	Err ors
8		
9		
10		
11		
12		
13		

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments
14	BRS	L14	4	3 and high adj corrosion	US- PGPUB ; USPAT ; DERWE NT	2004/12/0 6 11:02	
15	BRS	L15	3	3 and high adj corrosion adj resistance	US- PGPUB ; USPAT ; DERWE NT	2004/12/0 6 12:07	
16	BRS	L16	1	8 and high adj corrosion adj resistance	US- PGPUB ; USPAT ; DERWE NT	2004/12/0 6 11:05	
17	BRS	L17	0	3 and resist\$3 near3 corrosion	US- PGPUB ; USPAT ; DERWE NT	2004/12/0 6 12:08	
18	BRS	L18	16	3 and resist\$3 near3 corrosion	US- PGPUB ; USPAT ; DERWE NT	2004/12/0 6 12:08	
19	BRS	L19	1	4 and resist\$3 near3 corrosion	US- PGPUB ; USPAT ; DERWE NT	2004/12/0 6 12:11	

	Error Definition	Err ors
14		
15		
16		
17		
18		
19		

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comments
20	BRS	L20	7	3 and resist\$3 adj corrosion	US- PGPUB ; USPAT ; DERWE NT	2004/12/0 6 12:11	

	Error Definition	Err ors
20		